

1840 Stella Lake St. Las Vegas, NV 89106
Main 702-649-4616 Fax 702-649-4607
www.hitechnv.com service@hitechnv.com
Contractor's Lic #61023 & 77862 \$50,000.00 Lim

| Service Invoice | | |
|-----------------|-----------|--|
| Invoice # | WO-184473 | |
| Date | 8/25/2023 | |
| Due Date | 8/25/2023 | |
| Terms | COD | |
| Customer P.O. # | | |

BILL TO:

Joel Stolsky 2109 Broadway Apt 1141 New York, NY 10023 SERVICE SITE:

Joel Stolsky 2109 Broadway Apt 1141 New York, NY 10023

| Auth # | Technician | Equipment | Make | Model | Serial Number |
|--------|------------|-----------|-----------|----------|---------------|
| | Jason | Cooler | Turbo Air | MUF-60-N | Not provided |

| Qty | Item | Description | Loc | Rate | Amount |
|------|---------|---|----------|--------|----------|
| _ | | · | LUC | Nate | Alliount |
| | | Labor - Regular Time | | 124.00 | 434.00 |
| 1.00 | HTC1009 | EPA Recovery Charge (Recovery, Disposal, Vacuum, Torches) | 200 Reno | 125.00 | 125.00T |
| 1.00 | FGR290 | Propane Refrigerant R290 10.6 | 200 Reno | 111.60 | 111.60T |
| | | ***-Paid MasterCard \$670.60-*** | | | |
| | | Freezer is not turning on and cooling. Customer dropped off trailer and put each started to diagnose unit. Removed unit from the floor and moved out from the wall. Found unit almost flat. Added ports and found leak on high side process port. Repaired and pressurized unit to 200Psi, unit is holding. Vacuumed unit and added 2.5 Oz of R290. Tested unit is cooling for tech and customer. Placed unit back against the wall and secured to the ground. Completed. | | | |
| | | | | | |



^{*}All claims must be made in writing within 90 days of receipt of service.

^{*}A finance charge will be added to pay all collection and legal fees if such action be necessary in the amount of 1.5% per month on any past due invoices. In the event of a returned check or a non-sufficient fund transaction a flat rate of \$40.00 will be assessed as well.

*All pending part or service orders will be placed on hold if there is a past due balance owed.

| Subtotal | \$670.60 |
|------------------|-----------|
| Sales Tax (0.0%) | \$0.00 |
| Total | \$670.60 |
| Payments/Credits | -\$670.60 |

| Balance | Due | \$0.00 |
|----------------|-----|--------|
|----------------|-----|--------|

^{*}Special Order parts are non-refundable.

^{*}Customer assumes full responsibility to reimburse their service agency for parts and labor performed in these reports that are not covered by warranty