

Job Details

Future Turtles
130 Woodland Avenue
Reno, NV 89523

Billing Details

Accounts Payable
Future Turtles
130 Woodland Avenue
Reno, NV 89523

Amount Due

\$0.00

Date: 08/19/2025

19th August 2025

Make: Turbo air
Model Number: MUF-60-N
Serial Number:

Description of work

I arrived and checked in with management. He showed me to the freezer that was not getting to temperature. Upon arrival the reach in freezer was at 69 degrees F. I had to unbolt the feet from the floor to slide the unit out. Since everything was covered in a ton of dust. I cleaned out the condenser using water and co2. I energized the system and monitored. While monitoring I took an amp draw of the compressor. It was pulling 3.7 amps and in nominal. The condenser fan motor was pulling 0.8 amps and is nominal. After a few minutes the freezer did not pull down the temperature. I gauged up to the system. I was getting -9.2 inhg on the low side and 106.8 on the high side. The system is low on refrigerant. Using an electric leak detector I began searching for a leak. I did not get any indication of a leak on the system. I checked the condenser and all connections around the compressor. I checked the evaporator and all line set leading to the evaporator. I vacuumed the system down to 500 microns and preformed a decay test. I charged the system with 1 lb for R-134A. My pressures are now 5 psi on the low side and 134 on the high side. Upon departure the reach in freezer was at 27 degrees F. The system is now operational.

The customer also wanted me to clean the condensers for his walk in cooler and mini split. Using a hose and water I sprayed the condensers and removed a bunch of sand and debris.

Technician Name and Time:
Joseph 0700-1045=3.75hr

Work Approve By: pete

Description	Qty	Price	Total
Base Charge Refrigeration	1	\$40.00	\$40.00
Labor Standard Rate	3.75	\$110.00	\$412.50
CO2	1	\$40.00	\$40.00

HILLTOP

REFRIGERATION, INC.
HEATING AND AIR CONDITIONING

Invoice #41156

Remit: 1025 Telegraph Street
Reno, Nevada 89502
Office: 855-456-9836

Page 2 of 2

Evacuations	1	\$40.00	\$40.00
R-134A	1	\$32.50	\$32.50
Credit Card Process Fee 4%	1	\$22.97	\$22.97

Estimate amounts do not include tax and/or freight charges which will be added to the final invoice. 4% surcharge for all card transactions. Hilltop Refrigeration is a qualified warranty provider and as a courtesy to our customers, we will process and facilitate all necessary claim reporting to your warranty company on the customer's behalf. Your warranty company may or may not cover the entire service amount based on your warranty agreement guidelines. Customer will be responsible for any and all unpaid balance. Payment due within 30 days of invoice date with approved credit account. If customer does not have an approved credit account invoice is due upon receipt. \$30.00 late fee will apply every 30 days past due date. An additional charge of one third of the original bill will be added in the event any third parties are employed to collect any outstanding monies owed by said business the undersigned agrees to pay reasonable collection costs, including attorney fees, whether or not litigation has commenced, and all costs of litigation incurred. The undersigned represents that he/she has the authority to execute this credit agreement on behalf of the business identified. 30-day warranty.

Subtotal	\$587.97
Tax	\$9.31
Total	\$597.28
Amount Paid	-\$597.28
Balance Due	\$0.00

Customer: I acknowledge the terms, receipt of the materials and work described above.

Customer Signature